

Fire Risk Assessment 2016 recommendations

Fire Door Improvements / replacements

Public Hall - GROUND FLOOR

Long Room

- Double doors REPLACE to meet FD30(s)
- Door to office corridor IMPROVE to meet FD30(s)

Offices

- Office outer door IMPROVE to meet FD30(s)

Mayors Parlour

- Main door from foyer REPLACE to meet FD30(s)

Member's room lobby

- Keypad door to lobby REPLACE to meet FD30(s)

Under stage workshop

- Access ramp to main hall IMPROVE to meet FD30(s)

FIRST FLOOR

IMPROVE to meet FD30(s) :

- Doors into New Liskeard Room (2)
- Door to rear of stage
- Door to Refreshment room from rear corridor
- Double doors to Main Hall from Refreshment Room
- Double doors from Refreshment Room to top landing
- Main Hall Doors
- Door to Quimperle Room rear passageway from top landing
- Both doorways of the Quimperle Room
- Main door to Council Chamber
- Both entrance doors to main toilets
- Under stairs cupboard on half landing